

Environmental Testing Consultants, LLC

413 N. Black Horse Pike
Runnemede, New Jersey 08078

Phone: 856-482-1311
Fax: 856-312-8965

LEAD-BASED PAINT INSPECTION

**FORMER CHURCH RESIDENCE
317 LaREINE AVENUE
BRADLEY BEACH, NEW JERSEY**

Submitted to:

**Borough of Bradley Beach
701 Main Street
Bradley Beach, New Jersey 07720**

Submitted by:

**Environmental Testing Consultants, LLC
413 N. Black Horse Pike
Runnemede, New Jersey 08078**

856-482-1311



James Madden
New Jersey Lead Inspector/Risk Assessor
ID# 011653
September 16, 2020

TABLE OF CONTENTS

| | |
|------------------|---|
| SECTION 1 | EXECUTIVE SUMMARY |
| SECTION 2 | METHODOLOGIES/QUALITY CONTROL |
| SECTION 3 | RESULTS |
| SECTION 4 | LEAD CONTROL OPTIONS/RECOMMENDATIONS |
| SECTION 5 | ANALYTICAL |
| SECTION 6 | LICENSES |
| SECTION 7 | DRAWING |

EXECUTIVE SUMMARY

Environmental Testing Consultants, LLC (ETC) was contracted by the Borough of Bradley Beach to perform a lead-based paint (LBP) inspection of the Former Church Residence located at 317 LaReine Avenue, Bradley Beach, New Jersey.

This lead evaluation was undertaken pursuant to N.J.A.C. 5:10-1.10. A paint inspection is conducted to identify on a component by component basis where, and in what condition, LBP is present.

On site, the inspection consisted of:

1. XRF instrument
2. A visual assessment of paint condition.

Testing was completed by New Jersey Certified Lead Inspector/Risk Assessor James Madden (ID# 011653) on September 8, 2020.

ETC collected two hundred eight (208) XRF readings throughout the interior and exterior of the residence in completing this evaluation.

Findings indicate that lead in the amounts greater than or equal to 1.0 mg/cm² or greater than 0.5% by weight in paint was found on twenty (20) interior and exterior components using the protocol outlines in N.J.A.C. 5:17.

It is understood that all findings represent conditions at the time of testing. This report should be kept on file for the life of the facility.

ETC will be available to answer any questions you may have concerning this report.

METHODOLOGIES

A. XRF TESTING

The technology used for testing was the Niton XLP 306A X-Ray Fluorescence (XRF) Lead in Paint Spectrum Analyzer (Serial 23622) with a radioactive assay date of 4/26/13, and is considered state-of-the art equipment for measuring the level of lead in paint. All personnel operating the XRF analyzer received prior to training from Thermo Fisher Scientific, Inc.

The Performance Characteristic Sheet for the Niton XLP instrument states: XRF results are classified as positive if they are greater than or equal to the threshold, and negative if they are less than the threshold. Threshold range was determined by comparing results to the 1.0 mg/cm² standards.

QUALITY CONTROL

The calibration of the Niton XRF 306A is done in accordance with Performance Characteristic Sheets (PCS). The XRF instrument is calibrated using the paint film nearest 1.0 mg/cm² in the National Institute of Standards and Technology (NIST), Standard Reference Material (SRM) used. If readings are outside the acceptable calibration range, manufacturers recommendations are used to bring the instrument into calibration. If the instrument cannot be brought back into calibration, is removed from service and returned to manufacturer for examination, service and/or re-calibration.

Performance Characteristic Sheet

EFFECTIVE DATE: September 24, 2004

EDITION NO.: 1

MANUFACTURER AND MODEL:

Make: Niton LLC

Tested Model: XLP 300

Source: ¹⁰⁹Cd

Note: This PCS is also applicable to the equivalent model variations indicated below, for the Lead-in-Paint K+L variable reading time mode, in the XLI and XLP series:

XLI 300A, XLI 301A, XLI 302A and XLI 303A.

XLP 300A, XLP 301A, XLP 302A and XLP 303A.

XLI 700A, XLI 701A, XLI 702A and XLI 703A.

XLP 700A, XLP 701A, XLP 702A, and XLP 703A.

Note: The XLI and XLP versions refer to the shape of the handle part of the instrument. The differences in the model numbers reflect other modes available, in addition to Lead-in-Paint modes. The manufacturer states that specifications for these instruments are identical for the source, detector, and detector electronics relative to the Lead-in-Paint mode.

FIELD OPERATION GUIDANCE

OPERATING PARAMETERS:

Lead-in-Paint K+L variable reading time mode.

XRF CALIBRATION CHECK LIMITS:

0.8 to 1.2 mg/cm² (inclusive)

The calibration of the XRF instrument should be checked using the paint film nearest 1.0 mg/cm² in the NIST Standard Reference Material (SRM) used (e.g., for NIST SRM 2579, use the 1.02 mg/cm² film).

If readings are outside the acceptable calibration check range, follow the manufacturer's instructions to bring the instruments into control before XRF testing proceeds.

SUBSTRATE CORRECTION:

For XRF results using Lead-in-Paint K+L variable reading time mode, substrate correction is not needed for:
Brick, Concrete, Drywall, Metal, Plaster, and Wood

INCONCLUSIVE RANGE OR THRESHOLD:

| K+L MODE READING DESCRIPTION | SUBSTRATE | THRESHOLD (mg/cm ²) |
|---|-----------|------------------------------------|
| Results not corrected for substrate bias on any substrate | Brick | 1.0 |
| | Concrete | 1.0 |
| | Drywall | 1.0 |
| | Metal | 1.0 |
| | Plaster | 1.0 |
| | Wood | 1.0 |

BACKGROUND INFORMATION

EVALUATION DATA SOURCE AND DATE:

This sheet is supplemental information to be used in conjunction with Chapter 7 of the HUD *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing* ("HUD Guidelines"). Performance parameters shown on this sheet are calculated from the EPA/HUD evaluation using archived building components. Testing was conducted in August 2004 on 133 testing combinations. The instruments that were used to perform the testing had new sources; one instrument's was installed in November 2003 with 40 mCi initial strength, and the other's was installed June 2004 with 40 mCi initial strength.

OPERATING PARAMETERS:

Performance parameters shown in this sheet are applicable only when properly operating the instrument using the manufacturer's instructions and procedures described in Chapter 7 of the HUD Guidelines.

SUBSTRATE CORRECTION VALUE COMPUTATION:

Substrate correction is not needed for brick, concrete, drywall, metal, plaster or wood when using Lead-in-Paint K+L variable reading time mode, the normal operating mode for these instruments. If substrate correction is desired, refer to Chapter 7 of the HUD Guidelines for guidance on correcting XRF results for substrate bias.

EVALUATING THE QUALITY OF XRF TESTING:

Randomly select ten testing combinations for retesting from each house or from two randomly selected units in multifamily housing. Use the K+L variable time mode readings.

Conduct XRF retesting at the ten testing combinations selected for retesting.

Determine if the XRF testing in the units or house passed or failed the test by applying the steps below.

Compute the Retest Tolerance Limit by the following steps:

Determine XRF results for the original and retest XRF readings. Do not correct the original or retest results for substrate bias. In single-family housing a result is defined as the average of three readings. In multifamily housing, a result is a single reading. Therefore, there will be ten original and ten retest XRF results for each house or for the two selected units.

Calculate the average of the original XRF result and retest XRF result for each testing combination.

Square the average for each testing combination.

Add the ten squared averages together. Call this quantity C.

Multiply the number C by 0.0072. Call this quantity D.

Add the number 0.032 to D. Call this quantity E.

Take the square root of E. Call this quantity F.

Multiply F by 1.645. The result is the Retest Tolerance Limit.

Compute the average of all ten original XRF results.

Compute the average of all ten re-test XRF results.

Find the absolute difference of the two averages.

If the difference is less than the Retest Tolerance Limit, the inspection has passed the retest. If the difference of the overall averages equals or exceeds the Retest Tolerance Limit, this procedure should be repeated with ten new testing combinations. If the difference of the overall averages is equal to or greater than the Retest Tolerance Limit a second time, then the inspection should be considered deficient.

Use of this procedure is estimated to produce a spurious result approximately 1% of the time. That is, results of this procedure will call for further examination when no examination is warranted in approximately 1 out of 100 dwelling units tested.

TESTING TIMES:

For the Lead-in-Paint K+L variable reading time mode, the instrument continues to read until it is moved away from the testing surface, terminated by the user, or the instrument software indicates the reading is complete. The following table provides testing time information for this testing mode. The times have been adjusted for source decay, normalized to the initial source strengths as noted above. Source strength and type of substrate will affect actual testing times. At the time of testing, the instruments had source strengths of 26.6 and 36.6 mCi.

| Testing Times Using K+L Reading Mode (Seconds) | | | | | | |
|--|-----------------------------|--------|-----------------------------|--|-----------------|----------|
| Substrate | All Data | | | Median for laboratory-measured lead levels (mg/cm ²) | | |
| | 25 th Percentile | Median | 75 th Percentile | Pb < 0.25 | 0.25 ≤ Pb < 1.0 | 1.0 ≤ Pb |
| Wood Drywall | 4 | 11 | 19 | 11 | 15 | 11 |
| Metal | 4 | 12 | 18 | 9 | 12 | 14 |
| Brick Concrete Plaster | 8 | 16 | 22 | 15 | 18 | 16 |

CLASSIFICATION RESULTS:

XRF results are classified as positive if they are greater than or equal to the threshold, and negative if they are less than the threshold.

DOCUMENTATION:

A document titled *Methodology for XRF Performance Characteristic Sheets* provides an explanation of the statistical methodology used to construct the data in the sheets, and provides empirical results from using the recommended inconclusive ranges or thresholds for specific XRF instruments. For a copy of this document call the National Lead Information Center Clearinghouse at 1-800-424-LEAD.

This XRF Performance Characteristic Sheet was developed by the Midwest Research Institute (MRI) and QuanTech, Inc., under a contract between MRI and the XRF manufacturer. HUD has determined that the information provided here is acceptable when used as guidance in conjunction with Chapter 7, Lead-Based Paint Inspection, of HUD's *Guidelines for the Evaluation and Control of Lead-Based Paint Hazards in Housing*.

RESULTS

A. XRF TESTING

The U.S. Department of Housing and Urban Development (HUD), and the U.S. Environmental Protection Agency (EPA) established 1.0 mg/cm² or greater as a lead-based coating (dried film), as determined through the use of XRF instrumentation.

Included in this report are two (2) XRF Reports. The **Confirmed Positive Report** only shows positive readings that are equal to or greater than 1.0 mg/cm², the HUD/EPA regulatory standard (this report is omitted if no positive readings are found). The **XRF Results Report** lists all of the positive and negative readings taken and includes calibration readings collected at the beginning and end of the inspection on an NIST traceable paint film standard rated at 1.02 mg/cm².

A legend/floor plan designates "Wall 1" as the wall facing the street address. In a clockwise direction, "Wall 2" is to the left, "Wall 3" is the wall farthest from "Wall 1", and "Wall 4" is to the right. Doors, windows, and closets are designated as left, center, or right depending on their location on the wall, and a diagram of components is provided to identify areas tested.

The paint condition of all surfaces is rated in accordance with the criteria established in Chapter 5 - Table 5.3 "Conditions of Paint Film Quality" of the HUD Guidelines. The condition is rated as Good if the paint is in sound, intact condition, Fair if the paint has ≤10 ft² (exterior); ≤2 ft² (interior); or ≤10% (small components) of damage, and Poor if the paint has >10 ft² (exterior); >2 ft² (interior); >10% (small components).

It should be understood that when one (1) component was tested in a particular room, it is assumed that the one (1) component represents all like components in that particular room, with the exception of the walls. All four (4) walls in each particular room were tested in accordance with the HUD inspection protocol.

A total of 208 readings were collected from interior and exterior surfaces plus 10 calibration readings taken before, and at the end of the testing. Twenty (20) interior and exterior surface components were registered at or above the EPA regulatory limit of 1.0 mg/cm².

LBP could create lead dust hazards if the paint is deteriorated or is turned into dust by abrasion, scraping, or smudging.

For a complete listing of the positive results, see the "Confirmed Positive" Report.

LEGEND







WALL "1"

WALL "4"

WALL 1 = WALL FACING STREET ADDRESS
WALL 2 = LEFT SIDE
WALL 3 = ALWAYS FARTHEST FROM WALL "1"
WALL 4 = RIGHT SIDE

WALL "2"

WALL "3"



LEAD HAZARD CONTROL OPTIONS/RECOMMENDATIONS

The following abatement and interim controls are acceptable hazard control measures in accordance with the HUD Guidelines.

- 1. Remove and replace components with new energy efficient materials**
Component replacement is the most desirable abatement method because it offers a permanent solution to the lead-based paint problem. However, it is the most expensive method.
- 2. Chemically remove LBP from components or frictional/impact surfaces**
Chemical stripping results in less leaded dust generation than other removal methods. When chemical stripping is conducted on a wood substrate, it has been our experience that a primer will need to be applied following removal to achieve clearance. Observe all manufacturers' direction for use of paint removers.
- 3. Enclosure for walls, floors or impact surfaces**
Enclosure is the installation of a rigid, durable barrier that is mechanically attached to the building components. Paint deteriorates more quickly behind enclosure. All edges of an enclosure, especially the bottom, must be sealed well with caulking or other sealant.
- 4. Paint film stabilization, not an option for frictional/impact surfaces**
Paint stabilization can be achieved by wet scraping the loose cracked and chipping paint. Once any loose paint has been removed, clean the treated area with a HEPA vacuum. Use a tri-sodium phosphate (TSP) or suitable alternative to wash the treated areas. After the TSP wash, HEPA vacuum the treated areas again to capture any residual dust. Then perform a paint film stabilization by applying a primer and topcoat.
- 5. Manage in Place** indicates the Lead-Based Paint (LBP) on the components was in good condition and the components can be left in place without hazard response at this time.

It is recommended that each removable components that was confirmed positive for LBP should be removed and replaced. Any components that would call for excessive removal practices are to be contained using interim controls.

All of the painted surfaces where positive lead readings were recorded need to be maintained in "good" condition. Keep children away from areas where there is peeling, chipping or flaking paint.

All soft, movable or otherwise structurally unsound components should be repaired prior to any abatement or interim control.

After implementation of any lead hazard control option, reevaluation/clearance testing is needed to ensure lead hazards has been controlled.

CONFIRMED POSITIVE RESULTS

| Units | Component | Substrate | Side | Condition | Floor | Room | Results | Action Level | PbC | PbL | PbK |
|------------|--------------|-----------|------|--------------|-------|-------------|----------|--------------|-------|-------|-------|
| mg / cm ^2 | Baseboard | Wood | 1 | Deteriorated | 1 | Living Room | Positive | 1.00 | 9.80 | 2.80 | 9.80 |
| mg / cm ^2 | Window Sash | Wood | 4 | Deteriorated | 1 | Living Room | Positive | 1.00 | 29.10 | 7.10 | 29.10 |
| mg / cm ^2 | Baseboard | Wood | 2 | Deteriorated | 1 | Dining Room | Positive | 1.00 | 2.50 | 0.80 | 2.50 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | 1 | Dining Room | Positive | 1.00 | 24.50 | 10.10 | 24.50 |
| mg / cm ^2 | Baseboard | Wood | 1 | Intact | 1 | Kitchen | Positive | 1.00 | 4.70 | 4.70 | 5.20 |
| mg / cm ^2 | Window Case | Wood | 2 | Deteriorated | B | Basement | Positive | 1.00 | 27.70 | 10.10 | 27.70 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | B | Basement | Positive | 1.00 | 31.10 | 9.50 | 31.10 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | 1/2 | Stair #2 | Positive | 1.00 | 7.20 | 7.20 | 9.30 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | 2 | Hallway | Positive | 1.00 | 30.50 | 10.10 | 30.50 |
| mg / cm ^2 | Window Sill | Wood | 3 | Intact | 2 | Bedroom #1 | Positive | 1.00 | 3.80 | 3.80 | 3.40 |
| mg / cm ^2 | Window Sash | Wood | 3 | Deteriorated | 2 | Bedroom #1 | Positive | 1.00 | 30.50 | 10.10 | 30.50 |
| mg / cm ^2 | Window Apron | Wood | 3 | Intact | 2 | Bedroom #1 | Positive | 1.00 | 4.30 | 4.30 | 3.90 |
| mg / cm ^2 | Window Case | Wood | 3 | Intact | 2 | Bedroom #1 | Positive | 1.00 | 3.80 | 3.80 | 3.40 |
| mg / cm ^2 | Window Sash | Wood | 4 | Deteriorated | 2 | Bedroom #2 | Positive | 1.00 | 2.90 | 2.90 | 3.20 |
| mg / cm ^2 | Window Sash | Wood | 1 | Deteriorated | 2 | Bedroom #3 | Positive | 1.00 | 6.80 | 3.80 | 6.80 |
| mg / cm ^2 | Window Sash | Wood | 1 | Deteriorated | 2 | Bedroom #4 | Positive | 1.00 | 3.10 | 2.30 | 3.10 |
| mg / cm ^2 | Window Sash | Wood | 1 | Deteriorated | 3 | Bedroom #6 | Positive | 1.00 | 3.60 | 1.50 | 3.60 |
| mg / cm ^2 | Threshold | Wood | 1 | Deteriorated | 1 | Exterior | Positive | 1.00 | 23.10 | 6.60 | 23.10 |
| mg / cm ^2 | Door Case | Wood | 1 | Deteriorated | 1 | Exterior | Positive | 1.00 | 3.50 | 3.50 | 4.20 |
| mg / cm ^2 | Window Case | Wood | 2 | Deteriorated | 1 | Exterior | Positive | 1.00 | 27.50 | 8.80 | 27.50 |

XRF RESULTS

| Units | Component | Substrate | Side | Condition | Floor | Room | Results | Action Level | PbC | PbL | PbK |
|------------|--------------|--------------|------|--------------|-------|-------------|----------|--------------|-------|-------|-------|
| mg / cm ^2 | Wall | Plaster | 1 | Deteriorated | 1 | Living Room | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | Wall | Plaster | 2 | Deteriorated | 1 | Living Room | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Wall | Plaster | 3 | Deteriorated | 1 | Living Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Wall | Plaster | 4 | Deteriorated | 1 | Living Room | Negative | 1.00 | 0.17 | 0.17 | 0.60 |
| mg / cm ^2 | Ceiling | Ceiling Tile | 1 | Intact | 1 | Living Room | Negative | 1.00 | 0.00 | 0.00 | 0.08 |
| mg / cm ^2 | Baseboard | Wood | 1 | Deteriorated | 1 | Living Room | Positive | 1.00 | 9.80 | 2.80 | 9.80 |
| mg / cm ^2 | Door | Wood | 1 | Intact | 1 | Living Room | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | Door Jamb | Wood | 1 | Intact | 1 | Living Room | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Door Case | Wood | 1 | Intact | 1 | Living Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Window Sill | Wood | 4 | Intact | 1 | Living Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Window Apron | Wood | 4 | Intact | 1 | Living Room | Negative | 1.00 | 0.03 | 0.03 | 0.50 |
| mg / cm ^2 | Window Sash | Wood | 4 | Deteriorated | 1 | Living Room | Positive | 1.00 | 29.10 | 7.10 | 29.10 |
| mg / cm ^2 | Window Case | Wood | 4 | Intact | 1 | Living Room | Negative | 1.00 | 0.01 | 0.01 | 0.70 |
| mg / cm ^2 | Radiator | Metal | 4 | Intact | 1 | Living Room | Negative | 1.00 | 0.17 | 0.17 | 0.60 |
| mg / cm ^2 | Closet Wall | Plaster | 3 | Intact | 1 | Living Room | Negative | 1.00 | 0.07 | 0.07 | 0.50 |
| mg / cm ^2 | Shelf | Wood | 3 | Intact | 1 | Living Room | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | ShelfSupport | Wood | 3 | Intact | 1 | Living Room | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Closet Door | Wood | 3 | Intact | 1 | Living Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Closet Jamb | Wood | 3 | Intact | 1 | Living Room | Negative | 1.00 | 0.20 | 0.20 | 1.60 |
| mg / cm ^2 | Closet Case | Wood | 3 | Intact | 1 | Living Room | Negative | 1.00 | 0.03 | 0.03 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 1 | Dining Room | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 1 | Dining Room | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 1 | Dining Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 1 | Dining Room | Negative | 1.00 | 0.17 | 0.17 | 0.60 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 1 | Dining Room | Negative | 1.00 | 0.00 | 0.00 | 0.30 |
| mg / cm ^2 | Baseboard | Wood | 2 | Deteriorated | 1 | Dining Room | Positive | 1.00 | 2.50 | 0.80 | 2.50 |
| mg / cm ^2 | Window Sill | Wood | 2 | Intact | 1 | Dining Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Window Apron | Wood | 2 | Intact | 1 | Dining Room | Negative | 1.00 | 0.07 | 0.07 | 0.40 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | 1 | Dining Room | Positive | 1.00 | 24.50 | 10.10 | 24.50 |
| mg / cm ^2 | Window Case | Wood | 2 | Intact | 1 | Dining Room | Negative | 1.00 | 0.07 | 0.07 | 0.70 |
| mg / cm ^2 | Cabinet | Wood | 2 | Intact | 1 | Dining Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 1 | Kitchen | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 1 | Kitchen | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 1 | Kitchen | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 1 | Kitchen | Negative | 1.00 | 0.17 | 0.17 | 0.60 |
| mg / cm ^2 | Ceiling | Plaster | 2 | Intact | 1 | Kitchen | Negative | 1.00 | 0.07 | 0.07 | 0.50 |

| | | | | | | | | | | | |
|------------|--------------|-----------|---|--------------|-----|----------|----------|------|------|------|-------|
| mg / cm ^2 | Baseboard | Wood | 1 | Intact | 1 | Kitchen | Positive | 1.00 | 4.70 | 4.70 | 5.20 |
| mg / cm ^2 | Window Sill | Wood | 4 | Intact | 1 | Kitchen | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Window Apron | Wood | 4 | Intact | 1 | Kitchen | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Window Case | Wood | 4 | Intact | 1 | Kitchen | Negative | 1.00 | 0.02 | 0.02 | -0.08 |
| mg / cm ^2 | Wall | Sheetrock | 1 | Intact | 4 | Mud Room | Negative | 1.00 | 0.14 | 0.14 | 0.50 |
| mg / cm ^2 | Wall | Sheetrock | 2 | Intact | 4 | Mud Room | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Wall | Sheetrock | 3 | Intact | 4 | Mud Room | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Wall | Sheetrock | 4 | Intact | 4 | Mud Room | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Ceiling | Sheetrock | 2 | Intact | 4 | Mud Room | Negative | 1.00 | 0.02 | 0.02 | -0.08 |
| mg / cm ^2 | Baseboard | Wood | 2 | Intact | 4 | Mud Room | Negative | 1.00 | 0.02 | 0.02 | 0.23 |
| mg / cm ^2 | Door | Metal | 3 | Intact | 4 | Mud Room | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | Door Jamb | Wood | 3 | Intact | 4 | Mud Room | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Door Case | Wood | 3 | Intact | 4 | Mud Room | Negative | 1.00 | 0.03 | 0.03 | 0.40 |
| mg / cm ^2 | Wall | Sheetrock | 1 | Intact | 1 | Mud Room | Negative | 1.00 | 0.14 | 0.14 | 0.50 |
| mg / cm ^2 | Wall | Sheetrock | 2 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.02 | 0.02 | -0.08 |
| mg / cm ^2 | Wall | Sheetrock | 3 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.14 | 0.14 | 0.50 |
| mg / cm ^2 | Wall | Sheetrock | 4 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Ceiling | Sheetrock | 1 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Baseboard | Wood | 2 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Door | Wood | 2 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.02 | 0.02 | -0.08 |
| mg / cm ^2 | Door Jamb | Wood | 2 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.02 | 0.02 | 0.23 |
| mg / cm ^2 | Door Case | Wood | 2 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Window Case | Wood | 3 | Intact | 1 | Bath #1 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Wall | Plaster | 1 | Deteriorated | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Wall | Plaster | 2 | Deteriorated | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Wall | Plaster | 3 | Deteriorated | 1/B | Stair #1 | Negative | 1.00 | 0.14 | 0.14 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 4 | Deteriorated | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Deteriorated | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Door | Metal | 2 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Door Jamb | Wood | 2 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.02 | 0.02 | -0.08 |
| mg / cm ^2 | Door | Wood | 3 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.02 | 0.02 | 0.23 |
| mg / cm ^2 | Door Jamb | Wood | 3 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Door Case | Wood | 3 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Tread | Wood | 1 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.02 | 0.02 | 0.40 |
| mg / cm ^2 | Riser | Wood | 1 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.01 | 0.01 | 0.04 |
| mg / cm ^2 | Stringer | Wood | 1 | Intact | 1/B | Stair #1 | Negative | 1.00 | 0.02 | 0.02 | 0.60 |
| mg / cm ^2 | Wall | Block | 1 | Deteriorated | B | Basement | Negative | 1.00 | 0.03 | 0.03 | 0.40 |

| | | | | | | | | | | | |
|------------|---------------|---------|---|--------------|-----|----------|----------|------|-------|-------|-------|
| mg / cm ^2 | Wall | Block | 2 | Deteriorated | B | Basement | Negative | 1.00 | 0.14 | 0.14 | 0.50 |
| mg / cm ^2 | Wall | Block | 3 | Deteriorated | B | Basement | Negative | 1.00 | 0.02 | 0.02 | 0.08 |
| mg / cm ^2 | Wall | Block | 4 | Deteriorated | B | Basement | Negative | 1.00 | 0.02 | 0.02 | 0.23 |
| mg / cm ^2 | Window Case | Wood | 2 | Deteriorated | B | Basement | Positive | 1.00 | 27.70 | 10.10 | 27.70 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | B | Basement | Positive | 1.00 | 31.10 | 9.50 | 31.10 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.00 | 0.00 | 0.30 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.03 | 0.03 | 0.12 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.14 | 0.14 | 0.50 |
| mg / cm ^2 | Window Sill | Wood | 2 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.08 | 0.08 | 0.15 |
| mg / cm ^2 | Window Apron | Wood | 2 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.50 | 0.50 | 1.10 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | 1/2 | Stair #2 | Positive | 1.00 | 7.20 | 7.20 | 9.30 |
| mg / cm ^2 | Window Case | Wood | 2 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.02 | 0.02 | 0.11 |
| mg / cm ^2 | Tread | Wood | 1 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Riser | Wood | 1 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Stringer | Wood | 1 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Handrail | Wood | 1 | Intact | 1/2 | Stair #2 | Negative | 1.00 | 0.02 | 0.02 | 0.23 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 2 | Hallway | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 2 | Hallway | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Baseboard | Wood | 1 | Intact | 2 | Hallway | Negative | 1.00 | 0.03 | 0.03 | 0.12 |
| mg / cm ^2 | Window Sill | Wood | 2 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.30 |
| mg / cm ^2 | Window Apron | Wood | 2 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Window Sash | Wood | 2 | Deteriorated | 2 | Hallway | Positive | 1.00 | 30.50 | 10.10 | 30.50 |
| mg / cm ^2 | Closet Wall | Plaster | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.30 |
| mg / cm ^2 | Shelf | Wood | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Shelf Support | Wood | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Closet Door | Wood | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Closet Jamb | Wood | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Closet Case | Wood | 3 | Intact | 2 | Hallway | Negative | 1.00 | 0.29 | 0.29 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.02 | 0.02 | 0.11 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.00 | 0.00 | 0.40 |

| | | | | | | | | | | | |
|------------|---------------|---------|---|--------------|---|------------|----------|------|-------|-------|-------|
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.02 | 0.02 | 0.23 |
| mg / cm ^2 | Door | Wood | 1 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Door Jamb | Wood | 1 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Door Case | Wood | 1 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.01 | 0.01 | 0.26 |
| mg / cm ^2 | Window Sill | Wood | 3 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.06 | 0.06 | 0.40 |
| mg / cm ^2 | Window Case | Wood | 3 | Intact | 2 | Bath #2 | Negative | 1.00 | 0.20 | 0.20 | 0.30 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.00 | 0.00 | 0.30 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Baseboard | Wood | 2 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.06 | 0.06 | 0.50 |
| mg / cm ^2 | Door Jamb | Wood | 2 | Intact | 2 | Bedroom #1 | Negative | 1.00 | 0.00 | 0.00 | 0.40 |
| mg / cm ^2 | Window Sill | Wood | 3 | Intact | 2 | Bedroom #1 | Positive | 1.00 | 3.80 | 3.80 | 3.40 |
| mg / cm ^2 | Window Sash | Wood | 3 | Deteriorated | 2 | Bedroom #1 | Positive | 1.00 | 30.50 | 10.10 | 30.50 |
| mg / cm ^2 | Window Apron | Wood | 3 | Intact | 2 | Bedroom #1 | Positive | 1.00 | 4.30 | 4.30 | 3.90 |
| mg / cm ^2 | Window Case | Wood | 3 | Intact | 2 | Bedroom #1 | Positive | 1.00 | 3.80 | 3.80 | 3.40 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.14 | 0.14 | 0.17 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.18 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.20 | 0.20 | 0.30 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.30 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.17 |
| mg / cm ^2 | Baseboard | Wood | 2 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.18 | 0.18 | 0.60 |
| mg / cm ^2 | Door | Wood | 2 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.26 |
| mg / cm ^2 | Door Jamb | Wood | 2 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.27 |
| mg / cm ^2 | Door Case | Wood | 2 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.21 |
| mg / cm ^2 | Window Sash | Wood | 4 | Deteriorated | 2 | Bedroom #2 | Positive | 1.00 | 0.14 | 0.14 | 0.21 |
| mg / cm ^2 | Window Sill | Wood | 4 | Intact | 2 | Bedroom #2 | Positive | 1.00 | 2.90 | 2.90 | 3.20 |
| mg / cm ^2 | Closet Wall | Plaster | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.01 | 0.01 | 0.21 |
| mg / cm ^2 | Shelf | Wood | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.15 | 0.15 | 0.29 |
| mg / cm ^2 | Shelf Support | Wood | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.08 | 0.08 | 0.27 |
| mg / cm ^2 | Closet Door | Wood | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.08 | 0.08 | 0.50 |
| mg / cm ^2 | Closet Jamb | Wood | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.14 | 0.14 | 0.17 |
| mg / cm ^2 | Closet Case | Wood | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.00 | 0.00 | 0.18 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 2 | Bedroom #2 | Negative | 1.00 | 0.20 | 0.20 | 0.30 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.15 | 0.15 | 0.29 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.08 | 0.08 | 0.27 |

| | | | | | | | | | | | |
|------------|---------------|---------|---|--------------|-----|------------|----------|------|------|------|-------|
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.14 | 0.14 | 0.17 |
| mg / cm ^2 | Baseboard | Wood | 1 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.00 | 0.00 | 0.18 |
| mg / cm ^2 | Door | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.01 | 0.01 | 0.21 |
| mg / cm ^2 | Door Jamb | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.00 | 0.00 | 0.18 |
| mg / cm ^2 | Door Case | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.20 | 0.20 | 0.30 |
| mg / cm ^2 | Window Sill | Wood | 1 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.15 | 0.15 | 0.29 |
| mg / cm ^2 | Window Apron | Wood | 1 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.08 | 0.08 | 0.27 |
| mg / cm ^2 | Window Sash | Wood | 1 | Deteriorated | 2 | Bedroom #3 | Positive | 1.00 | 6.80 | 3.80 | 6.80 |
| mg / cm ^2 | Closet Wall | Plaster | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.15 | 0.15 | 0.29 |
| mg / cm ^2 | Shelf | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.00 | 0.00 | 0.18 |
| mg / cm ^2 | Shelf Support | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.20 | 0.20 | 0.30 |
| mg / cm ^2 | Closet Door | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.15 | 0.15 | 0.29 |
| mg / cm ^2 | Closet Jamb | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.08 | 0.08 | 0.27 |
| mg / cm ^2 | Closet Case | Wood | 3 | Intact | 2 | Bedroom #3 | Negative | 1.00 | 0.08 | 0.08 | 0.27 |
| mg / cm ^2 | Wall | Plaster | 1 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.26 | 0.26 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 2 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.00 | 0.00 | -0.29 |
| mg / cm ^2 | Wall | Plaster | 3 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.03 | 0.03 | 0.24 |
| mg / cm ^2 | Wall | Plaster | 4 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.00 | 0.00 | 0.14 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.00 | 0.00 | 0.24 |
| mg / cm ^2 | Baseboard | Wood | 3 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |
| mg / cm ^2 | Door | Wood | 3 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.09 | 0.09 | 0.03 |
| mg / cm ^2 | Door Jamb | Wood | 3 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |
| mg / cm ^2 | Door Case | Wood | 3 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.15 | 0.15 | 0.50 |
| mg / cm ^2 | Window Sill | Wood | 1 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.12 | 0.12 | 0.70 |
| mg / cm ^2 | Window Apron | Wood | 1 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.11 | 0.11 | 0.18 |
| mg / cm ^2 | Window Sash | Wood | 1 | Deteriorated | 2 | Bedroom #4 | Positive | 1.00 | 3.10 | 2.30 | 3.10 |
| mg / cm ^2 | Window Case | Wood | 1 | Intact | 2 | Bedroom #4 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 2 | Deteriorated | 2/3 | Stair #3 | Negative | 1.00 | 0.00 | 0.00 | -0.29 |
| mg / cm ^2 | Wall | Plaster | 3 | Deteriorated | 2/3 | Stair #3 | Negative | 1.00 | 0.03 | 0.03 | 0.24 |
| mg / cm ^2 | Wall | Plaster | 4 | Deteriorated | 2/3 | Stair #3 | Negative | 1.00 | 0.26 | 0.26 | 0.50 |
| mg / cm ^2 | Door | Wood | 2 | Intact | 2/3 | Stair #3 | Negative | 1.00 | 0.00 | 0.00 | -0.29 |
| mg / cm ^2 | Door Jamb | Wood | 2 | Intact | 2/3 | Stair #3 | Negative | 1.00 | 0.03 | 0.03 | 0.24 |
| mg / cm ^2 | Door Case | Wood | 3 | Intact | 2/3 | Stair #3 | Negative | 1.00 | 0.00 | 0.00 | 0.14 |
| mg / cm ^2 | Tread | Wood | 1 | Intact | 2/3 | Stair #3 | Negative | 1.00 | 0.00 | 0.00 | 0.24 |
| mg / cm ^2 | Riser | Wood | 1 | Intact | 2/3 | Stair #3 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |
| mg / cm ^2 | Stringer | Wood | 1 | Intact | 2/3 | Stair #3 | Negative | 1.00 | 0.00 | 0.00 | 0.14 |
| mg / cm ^2 | Wall | Plaster | 1 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |


| | | | | | | | | | | | |
|------------|--------------|---------|---|--------------|---|------------|----------|------|-------|------|-------|
| mg / cm ^2 | Wall | Plaster | 2 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.00 | 0.00 | -0.29 |
| mg / cm ^2 | Wall | Plaster | 3 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.03 | 0.03 | 0.24 |
| mg / cm ^2 | Wall | Plaster | 4 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.26 | 0.26 | 0.50 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.00 | 0.00 | -0.29 |
| mg / cm ^2 | Baseboard | Wood | 1 | Intact | 3 | Bedroom #5 | Negative | 1.00 | 0.03 | 0.03 | 0.24 |
| mg / cm ^2 | Window Sill | Wood | 3 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.00 | 0.00 | 0.14 |
| mg / cm ^2 | Window Apron | Wood | 3 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.00 | 0.00 | 0.24 |
| mg / cm ^2 | Window Sash | Wood | 3 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |
| mg / cm ^2 | Window Case | Wood | 3 | Deteriorated | 3 | Bedroom #5 | Negative | 1.00 | 0.00 | 0.00 | 0.24 |
| mg / cm ^2 | Wall | Plaster | 1 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.11 | 0.11 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 2 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.15 | 0.15 | 0.50 |
| mg / cm ^2 | Wall | Plaster | 3 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.12 | 0.12 | 0.70 |
| mg / cm ^2 | Wall | Plaster | 4 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.00 | 0.00 | -0.29 |
| mg / cm ^2 | Ceiling | Plaster | 1 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.03 | 0.03 | 0.24 |
| mg / cm ^2 | Baseboard | Wood | 1 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.00 | 0.00 | 0.14 |
| mg / cm ^2 | Window Sill | Wood | 1 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.00 | 0.00 | 0.24 |
| mg / cm ^2 | Window Apron | Wood | 1 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.16 | 0.16 | 0.60 |
| mg / cm ^2 | Window Case | Wood | 1 | Deteriorated | 3 | Bedroom #6 | Negative | 1.00 | 0.40 | 0.40 | 0.60 |
| mg / cm ^2 | Window Sash | Wood | 1 | Deteriorated | 3 | Bedroom #6 | Positive | 1.00 | 3.60 | 1.50 | 3.60 |
| mg / cm ^2 | Wall | Vinyl | 1 | Intact | 1 | Exterior | Negative | 1.00 | 0.16 | 0.16 | 0.60 |
| mg / cm ^2 | Threshold | Wood | 1 | Deteriorated | 1 | Exterior | Positive | 1.00 | 23.10 | 6.60 | 23.10 |
| mg / cm ^2 | Door Case | Wood | 1 | Deteriorated | 1 | Exterior | Positive | 1.00 | 3.50 | 3.50 | 4.20 |
| mg / cm ^2 | Window Case | Wood | 2 | Deteriorated | 1 | Exterior | Positive | 1.00 | 27.50 | 8.80 | 27.50 |
| mg / cm ^2 | Wall | Brick | 2 | Deteriorated | 3 | Exterior | Negative | 1.00 | 0.03 | 0.03 | 0.24 |

LICENSES

Lead Identification Permit

New Jersey Department of Health

JAMES N MADDEN




Permit No.: 035721
ID No.: 011653
Expires: 3/3/2022

Authorization Signature: *Christina Tan*
Christina Tan, MD, M.P.H., Assistant Commissioner

Inspector/Risk Assessor



New Jersey Department of Environmental Protection
 Bureau of Environmental Radiation
 Radioactive Materials Program
 Mail Code 25-01
 P.O. Box 420
 Trenton, NJ 08625-0420
 Phone (609) 984-5462
 Fax (609) 633-2210



Radioactive Materials License

Pursuant to the Radiation Protection Act (N.J.S.A. 26:2D) and the Radiation Code (N.J.A.C. 7:28, et seq.), as amended, and in reliance on statements and representations heretofore made by the licensee, a license is hereby issued authorizing the licensee to receive, acquire, possess, and transfer radioactive material(s) designated below; to use such material for the purpose(s) and at the place(s) designated below; to deliver or transfer such material to persons authorized to receive it in accordance with the regulations. This license is subject to all applicable rules, regulations, and orders of the New Jersey Department of Environmental Protection, now or hereafter in effect, and to any conditions specified below.

DOCUMENT INFORMATION

Program Interest (PI) ID: 425288

Issuance Date: 11/18/2019

License Number: 425288 - RAD190001

Expiration Date: 04/30/2023

ADMINISTRATIVE INFORMATION

Licensee Name and Administrative Address:
 ENVIRONMENTAL TESTING CONSULTANTS LLC
 413 N BLACK HORSE PK
 RUNNEMEDE, NJ 08078

Radiation Safety Officer:
 James Madden

PROGRAM INFORMATION

| Program Code | Description |
|--------------|--|
| 03122 | Measuring Systems Analytical Instruments |

LICENSE CONDITIONS

This license is subject to the following conditions:
 Section A – Authorized Materials, Form, Limits, Uses & Users
 Section B – Authorized Locations
 Section C – Source & Device Inventory
 Section D – Supporting Documents
 Section E – License Conditions

This license, which shall be effective immediately, is issued on behalf of the Department under the authority of:

Issued By: Sarah Adkisson
 Sarah Adkisson

Date: 11/18/2019

SECTION A – Materials, Form, Limits, Uses & Users

| Material | Form | Max Limit | Authorized Uses | Authorized Users |
|-------------|---------------|----------------|---|------------------|
| Cadmium-109 | Sealed Source | 50 millicuries | Non-Human Use - Sealed source(s) contained within a compatible device/gauge listed in Section C of this license document. | James Madden |
| Cobalt-57 | Sealed Source | 48 millicuries | | |

SECTION B – Authorized Locations

| Site ID | Site Name | Street Address | Location Description |
|---------|-----------------------------------|---|--|
| 496441 | ENVIRONMENTAL TESTING CONSULTANTS | 413 BLACKHORSE PK N RUNNEMEDE, NJ 08078 | Storage, Possession, Use: Designated device storage area |
| N/A | TEMPORARY JOB SITES | Temporary job sites wherever New Jersey retains regulatory authority. | Possession or Use Only (no storage) |

SECTION C – Source & Device Inventory

| ID | Device Type | Device Mfg | Device Model # | Device Serial # | Source Description |
|---------|--------------------|---------------------------------|----------------|-----------------|--|
| 935814 | X-Ray Fluorescence | EDAX Portable Products Division | Map 4 | M41505 | Co-57 - not to exceed 12 mCi per source: E.I. DuPont/New England Nuclear Model NER-472, Amersham Corporation Models CTC.D2 or CTC.D1, or Isotope Products Model PHI-XXX GFS. |
| 935815 | X-Ray Fluorescence | EDAX Portable Products Division | Map 4 | M41630 | |
| 935816 | X-Ray Fluorescence | EDAX Portable Products Division | Map 4 | M41276 | |
| 935817 | X-Ray Fluorescence | EDAX Portable Products Division | Map 4 | M41477 | |
| 1129128 | X-Ray Fluorescence | Thermo NITON Analyzers LLC | XLP 300A | 93088 | Cd-109 - not to exceed 50 mCi per source: QSA Global, Inc. Model CUC.D1 or CUC.P1, or Isotope Products Laboratories Model XFB-3 |

SECTION D – Supporting Documents

| Doc Type | Title/Description | Date | Contact Name (signature) |
|--|-------------------|------------|--------------------------|
| Radioactive Material License Application | NJ Application | 03/28/2013 | Howard Zenobi |
| Letter | RAI-RAD130001 | 06/18/2013 | Howard Zenobi |

SECTION E – License Conditions (Requirements Report attached)

ENVIRONMENTAL TESTING CONSULTANTS LLC
425288 RAD190001 RAD Materials License -Amended License
Requirements Report

Subject Item: PI 425288 -

1. This licensee must confine their use of radioactive materials to the materials, physical forms, maximum possession limits, authorized uses and authorized users listed in Section A of this license document. Licensed material shall only be used at the locations and/or within devices specified in Sections B and C of this license document. [N.J.A.C. 7:28-51.1]
2. The Radiation Safety Officer (RSO) specified in the Administrative Information section of this license document shall be responsible for ensuring that all individuals using the sealed source(s)/device(s) specified in this license are properly trained in the safe use and handling of the sealed source(s)/material(s). [N.J.A.C. 7:28-51.1]
3. Licensed material shall only be used by, or under the supervision and in the physical presence of, individuals who have received the training described in the correspondences specified in Section D of this license document. [N.J.A.C. 7:28-51.1]
4. Compliance with State and Federal agencies having jurisdiction and regulations for radioactive materials must be maintained. [N.J.A.C. 7:28-51.1]
5.
 - (A) Sealed sources shall be tested for leakage and/or contamination at intervals not to exceed the intervals specified in the certificate of registration issued by the U.S. Nuclear Regulatory Commission under 10 CFR 32.210 or by an Agreement State.
 - (B) In the absence of a certificate of registration issued by the U.S. Nuclear Regulatory Commission under 10 CFR 32.210 or by an Agreement State, sealed sources shall be tested for leakage and/or contamination at intervals not to exceed 6 months.
 - (C) Notwithstanding Paragraphs A and B of this Condition, sealed sources designed to primarily emit alpha particles shall be tested for leakage and/or contamination at intervals not to exceed 3 months.
 - (D) In the absence of a certificate from a transferor indicating that a leak test has been made within the intervals specified in the certificate of registration issued by the U.S. Nuclear Regulatory Commission under 10 CFR 32.210 or by an Agreement State prior to the transfer, a sealed source or detector cell received from another person shall not be put into use until tested.
 - (E) Sealed sources need not be tested if they contain only hydrogen-3; or they contain only a radioactive gas; or the half-life of the isotope is 30 days or less; or they contain not more than 100 microcuries of beta- and/or gamma-emitting material or not more than 10 microcuries of alpha-emitting material.
 - (F) Sealed sources need not be tested if they are in storage and are not being used. However, when they are removed from storage for use or transferred to another person, and have not been tested within the required leak test interval, they shall be tested before use or transfer. No sealed source shall be stored for a period of more than 10 years without being tested for leakage and/or contamination. [N.J.A.C. 7:28-51.1]

ENVIRONMENTAL TESTING CONSULTANTS LLC
425288 RAD190001 RAD Materials License -Amended License
Requirements Report

Subject Item: PI 425288 -

6. (A) Sealed source leak tests shall be capable of detecting the presence of 0.005 microcurie (185 becquerels) of radioactive material on the test sample. If the test reveals the presence of 0.005 microcurie (185 becquerels) or more of removable contamination, a report shall be filed with the Department in accordance with N.J.A.C. 7:28-51.1 [10 CFR 30.50(c)(2)] and the source shall be removed immediately from service and decontaminated, repaired, or disposed of in accordance with Department regulations.
(B) Tests for leakage and/or contamination, limited to leak test sample collection, shall be performed by the licensee or by other persons specifically licensed by the Department, the U.S. Nuclear Regulatory Commission or an Agreement State to perform such services. The licensee is not authorized to perform the analysis; analysis of leak test samples must be performed by persons specifically licensed by the Department, the NRC or an Agreement State to perform such services.
(C) Records of leak test results shall be kept in units of microcuries and shall be maintained for 3 years. [N.J.A.C. 7:28-51.1]
7. Except for maintaining labeling as required by N.J.A.C. 7:28-6.1 or 61.1 (10 CFR Part 20 or 71), the licensee shall obtain authorization from the U.S. Nuclear Regulatory Commission or Agreement State before making any changes in the sealed source, device, or source-device combination that would alter the description or specifications as indicated in the respective Registration Certificates issued either by the Commission pursuant to 10 CFR 32.210 or by an Agreement State. [N.J.A.C. 7:28-51.1]
8. Each portable device shall have a lock or outer locked container designed to prevent unauthorized or accidental removal of the sealed source from its shielded position. The gauge or its container must be locked when in transport, storage or when not under the direct surveillance of an authorized user. [N.J.A.C. 7:28-51.1]
9. Any cleaning, maintenance, or repair of the gauge(s) that requires detaching the source from the gauge shall be performed only by the manufacturer or by other persons specifically licensed by the Department, the NRC or an Agreement State to perform such services. [N.J.A.C. 7:28-51.1]
10. The device(s)/sealed source(s) specified in this license shall be stored and transported in a manner to ensure against unauthorized handling, possession or removal of radioactive materials. The device(s)/source(s) shall be stored and transported in a manner optimizing the distance between the device and personnel. The licensee is authorized to transport licensed material only in accordance with the provisions of N.J.A.C. 7:28-61.1 (10 CFR Part 71), Packaging and Transportation of Radioactive Material. [N.J.A.C. 7:28-51.1]
11. The licensee shall conduct a physical inventory every six months, or at other interval approved by the Department, to account for all sealed sources and/or devices received and possessed under the license. Records of inventories shall be maintained for 3 years from the date of each inventory and shall include radionuclides, quantities, manufacturer's name and model numbers, serial numbers and the date of the inventory. [N.J.A.C. 7:28-51.1]
12. Except as specifically provided otherwise in this license, the licensee shall conduct its program in accordance with the statements, representations, and procedures contained in the documents, including any enclosures, specified in Section D of this license document. [N.J.A.C. 7:28-51.1]



PHILIP D. MURPHY

Governor
LOCATION
101 S BROAD ST
TRENTON NJ 08608

STATE OF NEW JERSEY
DEPARTMENT OF COMMUNITY AFFAIRS
DIVISION OF CODES AND STANDARDS
LEAD HAZARD UNIT

LT. GOVERNOR SHEILA Y. OLIVER

Commissioner
MAILING ADDRESS
101 S BROAD ST
TRENTON NJ 08618

Certificate - Lead Evaluation Contractor

RECERTIFIED

This is to certify that the Department of Community Affairs has certified


ENV. TESTING CONSULTANTS, LLC
413 NORTH BLACK HORSE PIKE
RUNNEMEDE NJ 08078

To act as a Lead Evaluation Contractor on the following Projects


Residential
Public Buildings
Comm/Steel Structure

Cert #: 00335-E
Effective Date: 1/1/2020
Expiration Date: 12/31/2021
Certificate Type: 2 YEAR


DRAWING




FIRST FLOOR



BASEMENT



SECOND FLOOR



THIRD FLOOR

Environmental Testing Consultants, LLC
 413 N. Black Horse Pike
 Runnemede, New Jersey 08078
 856-482-1311

317 LaREINE AVENUE
 BRADLEY BEACH, NEW JERSEY

E20-0817-01

SCALE: NTS

CHK BY:

DWG. BY:

SK-1